

SPECIALTY WORKWEAR

Heat & Hydration Accessories

Chill-Its 6250 Phase Change Cooling Vest Ice Packs (4-Pack)







HOW TO CLEAN

The cooling pack should be washed by hand with a mild detergent and warm water. Dry with a paper towel or cloth. DO NOT machine wash or machine dry. Ideal for workers in need of cooling relief but aren't able to use an evaporative cooling option.

- IMMEDIATE & LONG-LASTING COOLING RELIEF Packs maintain constant 18° C for up to 2 hours
- QUICK RECHARGE Cooling packs reactivate in as little as 5 minutes
- **LIGHTWEIGHT** 30%-60% lighter weight than other cooling vests
- **ENVIRONMENTALLY FRIENDLY** 100% biodegradable phase change cooling material
- FLEXIBLE Grid ice pack design eliminates stiffness
- **EXTRA STORAGE** Two zippered front pockets
- FLEXIBLE FIT Adjustable hook and loop closures on waist for
- **EASY ON/OFF** Heavy-duty zipper closure on the front of vest
- **COMFORTABLE** Polvester cotton blend construction
- **VEST SOLD SEPARATELY**

The Ergodyne Chill-Its Lightweight Phase Change Cooling Vest Ice Packs (4-Pack) are made to be inserted into model 6260 Lightweight Phase Change Cooling Vest to keep workers cooler, safer and more productive. The phase change cooling material in the packs is 100% biodegradable and maintain a 18° C temperature for up to 2 hours when activated. These packs are designed to be 30%-60% lighter weight than other cooling vests on the market.

HOW TO USE

Purchase the lightweight vest with packs or purchase the Lightweight Vest separately. There are many ways to activate your cooling vest. Simply place the two removable packs in a cooler of ice water for 5 minutes; freezer for 8 minutes; refrigerator for 12 minutes; or near an air conditioner for 1 hour. Then place the recharged cooling packs in the vest pockets for hours of cooling.



DIMENSIONS

Fits 6250 Lightweight Phase Change Cooling Vest



SCAN TO ORDER

PART NO.	DESCRIPTION
12120	Chill-Its 6250 Phase Change Cooling Vest Ice Packs (4-Pack)

